

## Coil Spring Replacement

MAKE/MODEL

**2022-On P703 FORD RANGER RAPTOR**

No.

**FWB-013A**

Symptoms:

Harsh ride after installing raised springs will occur if FOX Shocks aren't re-calibrated.

Causes:

The FOX Shocks on these vehicles are continually monitoring the piston position from within the shock to calculate ride heights. When raised springs are installed it changes the base setting of these ride heights causing the computer to not function correctly and deliver a harsh ride.

Rectification:

FORD VDM Ride Height Calibration is required using the FORD FORSCAN software. Refer to FWB-013B or contact a Fulcrum Suspensions workshop.