

IMPORTANT NOTICE -

Z6102

Fitment of ZEDER upper control arms to vehicles that have lifts fitted greater than a 50mm (2 inch) height may suffer from premature ball joint failure if droop length exceeds specification listed in the RVD. The use of strut spacers may also effect the performance and longevity of the UCA ball joint due to the limitations of the spherical bearing housing being breached or bound at full suspension droop. There will be no warranty either expressed or implied if the vehicle is used out of legal driving conditions that will include but is not limited to jumping of the vehicle.

Copyright ABN 99 124 177 297