



SAVE UP TO TWO HOURS WITH OUR NEW SPLIT BOOT KIT.

The thinking behind Toyota's innovative Split Boot Kit is so simple you'll wonder why no-one's ever thought of it before. Rather than having to remove an entire drive shaft to replace a worn boot kit, the Toyota Genuine Split Boot Kit makes preventative maintenance so much easier. It simply fits around the drive shaft and is then firmly sealed with an ingenious snap-fit connection. And since you can do so in less than 30 minutes, you will have more time to service and repair even more vehicles.

THINK OF THE BENEFITS:

- Split Boot Kits are competitively priced.
- Your customers will be happier because they won't be inconvenienced by having their cars off the road for lengthy periods of time.
- And better still, the "93 Point Inspection" featuring CV joint inspection will help you raise customer awareness of preventative maintenance.

But saving time doesn't mean sacrificing quality. These Split Boot Kits are as thick as the original Toyota Genuine Boot so they're equally durable and puncture resistant.

FITTING A SPLIT BOOT KIT IS EASY. HERE ARE SOME HELPFUL HINTS TO GET YOU STARTED:

- Once all the excess grease from the old boot is removed, use the grease shield provided as part of the SBK packaging.
- Apply the lubricant provided to the groove side of the boot split.
- Always start at the large end of the SBK when joining the split.
- Always test the joint after connection by pulling apart to ensure correct joining.
- Fasten the small end of the boot to the shaft with the clamp provided before applying the grease provided.
- Always apply the fastening side of the clamps 180 degrees from the boot split joint.

So next time you need to replace a worn boot kit, use the Toyota Genuine Split Boot Kit and reap the benefits.

MAIN MODELS	MODEL CODE	PRODUCTION	MVP No
AVALON	MCX10	April 2000 - Jun 2006	04438-YZZ19
AVENSIS-VERSO	ACM2#	May 2001-	04438-YZZ17
CAMRY	MCV20, MCV36 Manual	Aug 2002 - Dec 2003	04438-YZZ18
CAMRY	SXV20, ACV36 Manual, MCV36 Automatic	Aug 2002 - Jun 2006	04438-YZZ19
CAMRY	ACV36 Automatic	Aug 2002 - Jun 2006	04438-YZZ21
CELICA	ST204 - Automatic	May 1998 - Nov 1999	04438-YZZ03
CELICA	ST204 - Manual	Nov 1993 - May 1998	04438-YZZ05
CELICA	ST205, ZZT231	Apr 1996 -Sep 2005	04438-YZZ16
COROLLA	AEII2	Aug 1998 - Jan 1999	04438-YZZ03
COROLLA	AEII2	Jan 1999 - Sep 2001	04438-YZZ04
COROLLA	ZZE122	Oct 2001 - Sep 2006	04438-YZZ04
ECHO	NCP10	Aug 1999 - Jun 2002	04438-YZZB2
ECHO	NCPJ0	Jun 2002 - Aug 2005	04438-YZZB3
ECHO	NCP12, NCP13, NCP10 (type A shaft)	Nov 1999 - Aug 2005	04438-YZZ14
HILUX	RZN169/174,VZN167	Aug 1997 - Jun 2005	04438-YZZ06
KLUGER	MCU28	Aug 2003 - Aug 2004	04438-YZZ17
LAND CRUISER 100	HDJ100, UZJ100	Oct 1998 - May 2005	04438-YZZ15
LAND CRUISER PRADO	GRJ95, RZJ95, KZJ95, VZJ95	Apr 1996 - Sep 2002	04438-YZZ09
LAND CRUISER PRADO	GRJ120, RZJ120, KZJ120, KDJ120	Sep 2002 - Jul 2009	04438-YZZ20
PASEO	EL54	Aug 1995 - Jul 1999	04438-YZZ02
PRIUS	NHWJI	Aug 2001 - Aug 2003	04438-YZZ04
PRIUS	NHW20	Aug 2003 - Mar 2006	04438-YZZ14
RAV4	SXAI#	Jun 1994 - Jan 1999	04438-YZZ03
RAV4	SXAI#	Jan 1999 - May 2000	04438-YZZ04
RAV4	ACA2#	May 2000 - Nov 2005	04438-YZZ17
STARLET	EP9 I	Jan 1996 - Jul 1999	04438-YZZ02
TARAGO	ACR30	Feb 2000 - Jul 2002	04438-YZZ17
YARIS	NCP9#	Oct 2005 - Aug 2008	04438-YZZ14







Please note: As the Split Boot Kit is a preventative maintenance part and not an original equipment replacement part, it cannot be fitted and used without affecting the manufacturer's new vehicle warranty. All Toyota Genuine Parts do however carry a 12 month (unlimited kilometres) Toyota warranty against manufacturing defects.

^{*04438-}YZZ19 will not fit the SXV20 if the Genuine replacement outer joint has been fitted.