

NISSAN PINTARA & SKYLINE R31

WARNING

When removing old bushes from lower trailing arm ensure the outer shells of the bush remain in the arm. The replacement bushes will then press into these shells remaining in the arm.

Failure to follow this warning will result in the arms being unserviceable as the outside diameter of the replacement bushes will not be able to locate properly.